



SUPERVISOR'S DECLARATION

I hereby declare that I have checked this thesis and in my opinion, this thesis is adequate in terms of scope and quality for the award of the degree of the degree of Barchelor (Hons.) of Civil Engineering

A handwritten signature in black ink, appearing to be 'Pn. Nadiatul Adilah Binti Ahmad Abdul Ghani', is written over a horizontal line.

(Supervisor's Signature)

Full Name : Pn. Nadiatul Adilah Binti Ahmad Abdul Ghani

Position : Lecturer

Date : 19th June 2017



STUDENT'S DECLARATION

I hereby declare that the work in this thesis is based on my original work except for quotations and citations which have been duly acknowledged. I also declare that it has not been previously or concurrently submitted for any other degree at University Malaysia Pahang or any other institutions.



(Student's Signature)

Full Name : ABDUL RAZAK BIN MOHAMAD GHAZI

ID Number : AA13024

Date : 19 JUNE 2

EFFECT OF RIVER MORPHOLOGY IN SUNGAI JEMBERAU AT TASIK CHINI
DUE TO UPLAND ACTIVITIES

ABDUL RAZAK BIN MOHAMAD GHAZI

Thesis submitted in fulfillment of the requirements
for the award of the
Bachelor Degree in Civil Engineering

Faculty of Civil Engineering and Earth Resources

UNIVERSITI MALAYSIA PAHANG

JUNE 2017

PERPUSTAKAAN UNIVERSITI MALAYSIA PAHANG	
No. Perolehan 121010	No. Panggilan FFASA
Tarikh 23 NOV 2017	RBG 2017 v Be.

ACKNOWLEDGEMENTS

Firstly, all Praise be upon Allah, the Al Mighty, and peace and prosperity to the noble Prophet, his family, his companions and upon those who follow his path and guide. As depend on Him, I managed to complete the research successfully.

Secondly, from the beginning until the completion of this research, my genuine appreciation and grateful thanks goes to my supervisor, Pn. Nadiatul Adilah Bt. Ahmad Abdul Ghani from Faculty of Civil Engineering & Earth Resources, Universiti Malaysia Pahang for her kindness in helping me understanding the whole process in completing this thesis. Thanks for reading, feedback, support and advice for me in order to finish my research.

Thirdly, I would like to express my gratitude to Department of Irrigation and Drainage (DID) staffs, for assisting and cooperation toward me during my research time. My gratitude also to all lecturers, who involved directly or indirectly, for their encouragement support, advice, and sharing knowledge regarding on my research.

Next, a special thanks to everyone that had involved directly or indirectly in my research. Thanks for your kindness. Last but not least, a special thanks to my family for the continuous support and encouragement.

ABSTRAK

Satu kajian mengenai morfologi sungai telah dijalankan di Sungai Jemberau, Pahang. Kajian ini tertumpu kepada perubahan morfologi sungai dengan menentukan masalah berdasarkan perubahan morfologi di lokasi tertentu untuk mentafsirkan faktor yang menyebabkan perubahan sungai pada setiap peringkat morfologi. Beberapa pendekatan telah digunakan dalam kajian ini. Pertama, ia melibatkan fasa kajian perancangan dan pembacaan dari sumber bertulis. Kedua, ia adalah satu pendekatan yang digunakan untuk pengumpulan data dan maklumat diikuti oleh pelaksanaan teknik pembelajaran. Kawasan kajian adalah salah satu sungai yang mengalir air ke kawasan tadahan Tasik Chini. Keputusan yang dijangkakan untuk perubahan morfologi dikumpul dan analisis dari peta Google Earth. Dari peta Google Earth, perubahan sungai boleh dilihat bermula daripada tahun 2011 sehingga tahun 2017. Dalam peringkat pengumpulan data, keratan rentas di saluran sungai digunakan untuk mengenal pasti semua perubahan morfologi sungai pada tahun 2017. Kajian ini dijalankan untuk mengenal pasti ciri-ciri sungai faktor yang mempengaruhi hakisan berlaku dan perubahan luas keratan rentas. Selain itu, ia juga boleh digunakan untuk mengenal pasti masalah tersebut berdasarkan perubahan morfologi di lokasi tertentu. Malah boleh digunakan oleh pihak berkaitan untuk sebarang rujukan dalam penyelidikan mereka. Akhir sekali, pihak berkuasa tempatan boleh melaksanakan penyelesaian yang sesuai untuk mengurangkan risiko kejadian banjir.

ABSTRACT

Study on river morphology was conducted at Sungai Jemberau, Pahang. This study focused on changes of river morphology by determine the problems based on the changes of morphology at specific location and to interpret the responsible factors that caused the changes of river morphology. Several stages and approaches have been used. First, it involves the phase of planning studies and literature. Secondly, it is an approach used for data collection and information followed by the implementation of learning techniques. The study area is about the river in Tasik Chini catchment area. Expected results for morphology changes are collected and analysis from the Google Earth Maps. From the Google Earth Maps, the changes of river can be seen from year 2010 until year 2017. There are several stage records available in the study. Cross-section across river channel of the river is used to identify all changes of river morphology In year 2017. This study was carried out to identify the river characteristic of the factor affecting erosion occurs and the changes of cross sectional area . Besides that, it can be used to identify the problem based on the changes of morphology at specific location. Other than that, it can be used by other parties to make reference in their research. Lastly, local authorities can implemented appropriate solution to reduce the flood event's risks

TABLE OF CONTENT

DECLARATION

TITLE PAGE

ACKNOWLEDGEMENTS **ii**

ABSTRAK **iii**

ABSTRACT **iv**

TABLE OF CONTENT **v**

LIST OF TABLES **ixiii**

LIST OF FIGURES **ix**

CHAPTER 1 INTRODUCTION **1**

1.1 Background Of Study 1

1.2 Problem Statement 2

1.3 Objective Of Study 2

1.4 Scope Of Study 3

1.5 Significant Of Study 3

CHAPTER 2 STYLES **4**

2.1 Introduction 4

2.2 River Morphology 5

2.3 Characteristic Of The River 6

2.3.1 Shape Of The River 6

2.3.2 Stream Classification 7

2.4	Sediment	7
2.4.1	Climate	8
2.4.2	Topography	8
2.4.3	Land Use	9
2.5	Rainfall	10
CHAPTER 3 METHODOLOGY		11
3.1	Introduction	11
3.2	Google Earth	16
3.3	Data Collection	17
3.3	River Area Measurement	17
CHAPTER 4 RESULTS AND DISCUSSION		20
4.1	Introduction	20
4.2	Data Analysis	20
4.3	Field Measurement	21
4.4	Google Earth	22
4.5	River Morphology	22
4.5.1	Station 1	25
4.5.2	Station 2	25
4.5.3	Station 3	26
4.5.4	Station 4	26
4.5.5	Station 5	27

4.5.6	Station 6	28
4.5.7	Prediction	29
4.6	River Area Measurement	31
4.7	Cross Sectional Area	32
4.7.1	Mechanical Sieve Analysis	29
4.8	Soil Properties Particle Distribution	37
4.8.1	Soil Properties Particle Distribution for Sample 1 (24th November 2016)	37
4.8.2	Soil Properties Particle Distribution for Sample 2 (1th December 2016)	39
4.8.3	Soil Properties Particle Distribution for Sample 3 (5th March 2017)	41
4.8.4	Soil Properties Particle Distribution for Sample 4 (17th May 2017)	43
CHAPTER 5 CONCLUSION AND RECOMMENDATION		46
5.1	Conclusion	46
5.1	Recommendation	47
REFERENCES		49
APPENDIX A NEWSPAPER CUTTING		50
Figure A.1	Harian Metro 25 February 2017 (sheet 1)	50
Figure A.2	Harian Metro 25 February 2017 (sheet 2)	51
Figure A.3	New Straits Times 17 March 2017	52

APPENDIX B FLOOD PICTURE	53
---------------------------------	-----------

Figure B.1	Flood In Sungai Chini	53
------------	-----------------------	----

Figure B.2	Flood in the village of Orang Asli	44
------------	------------------------------------	----

LIST OF TABLES

Table 4.1	Flow rate data calculation by using Mean Section Method	31
Table 4.2	Result uniformity coefficient and coefficient of gradation	34
Table 4.3	Relationship between flow rate and rainfall	36
Table 4.4	Bedload concentration calculation	36
Table 4.5	Sieve Analysis at Sample 1, Sunny Day	37
Table 4.6	Sieve Analysis for Sample 2, Sunny Day	39
Table 4.7	Sieve Analysis for Sample 3, Sunny Day	41
Table 4.8	Sieve Analysis for Sample 4, Sunny Day	43

LIST OF FIGURES

Figure 2.1	Rosgen Classification. 2007 Longitudinal , coss section and plan views of major stream types	7
Figure 3.1	Location of study area	12
Figure 3.2	List Of The River Plan In Tasik Chini	12
Figure 3.3	Flow chart of study	13
Figure 3.4	Methodology flow chart	15
Figure 3.5	Aluminium Staff	18
Figure 3.6	Laser Distance	18
Figure 3.7	Measuring work to determine width of the section	19
Figure 4.1	Placemark Coordinate in Tasik Chini	23
Figure 4.2	The deformation of Tasik Chini for year 1984, 2011, 2013, 2016	24
Figure 4.3	The changes of the river at Sungai Chini in year 2011-2012-2014	25
Figure 4.4	The changes of the river at Sungai Celau in year 2011-2012-2014	25
Figure 4.5	The changes of the river at Sg Perupok/ Sg Chok/ Sg Melai (up/downstream) in year 2011-2012-2014	26
Figure 4.6	The changes of the river at Sungai Kenawar/ Sungai Serodong in year 2011-2012-2014	27
Figure 4.7	The changes of the river at Sg Gumum in year 2011-2012-2014	27
Figure 4.8	The changes of the river at Sungai Jemberau in year 2011-2012-2014	28

Figure 4.9	The sketch deformation in year 2011-2012-2014 of the river at Sungai Jemberau	29
Figure 4.10	Example illustration of the cross section at the station	32
Figure 4.11	Particle size distribution curve for soil sample soil trap	32
Figure 4.12	Particle size distribution curve for soil sample riverside	33
Figure 4.13	Particle size distribution curve for soil sample in the river	33
Figure 4.14	View of the river with low rainfall volume	35
Figure 4.15	View of the river during high rainfall volume	35
Figure 4.16	Grain Distribution for Sample 1,(24th November 2016	38
Figure 4.17	Grain Distribution for Sample 2, (1st December 2016)	40
Figure 4.18	Grain Distribution for Sample 3, (5th March 2017)	42
Figure 4.19	Grain Distribution for Sample 4 (17th May 2017)	44
Figure 4.20	Landslip near the river	45
Figure 4.21	Erosion view of the river	45

CHAPTER 1

INTRODUCTION

1.1 Background of Study

Rain water flowing down slopes comes together to form a stream flow. The space where a stream flow runs is a channel. A river is the general term for a channel and the water in it. The area supplying water into a channel is a drainage basin. The boundary between drainage basins is a water divide. A river system is composed of the main stream and many tributaries. However, there are many cases where several tributaries have similar length and flow, and it is difficult to determine which is the main stream. A drainage pattern is a plan of a river system. A river develops various landforms through channel processes.

Sediment is the nonpoint source pollutant originated from various sources and washed into our waterways by surface runoff . When land disturbing activities occur, soil particles are transported by surface water movement. Soil particles transported by water are often deposited in streams, lakes and wetlands that can changes the cross section, increase the bed load also changes the morphology. It also will make the quantity of aquatic life will reduce . The process of sediment deposition is also dependent on river discharge and speed of river flow. As such, the higher value of water velocity would result in higher amount of sediment.

1.2 Problem Statement

Tasik Chini is a fresh-water lake in the West-Malaysian state of Pahang. Though still enchanting, the lake has suffered and still suffers from activities outside the control of the local Orang Asli. Since the 1970s, erosion sediments (including chemicals) due to logging, heavy metal mining, and palm oil plantations enter the lake via its tributaries, troubling the once clear water of the lake. Through seasonal flushing, the lake seemed able to survive this first blow.

Several major floods happened in the most recent couple of decades in Kuantan, not just bringing extensive damage and inconvenience to the community or the economic, additionally the stream morphology itself. The sediment will reduce the function of the river and will cause flooding and brings along the sediments from upstream to downstream when receives heavy rainfall during monsoon time.

1.3 Objective of Study

The objectives of this study are:

- 1 To identify land used area in Tasik Chini and effect to river morphology by comparisons of satellite images in 6 years duration from 2011 to 2017
- 2 To study the morphology and river characteristics in Sungai Jemberau at Tasik Chini due to sedimentation and upland activities

1.4 Scope of Study

A study area for this project was located in Sg. Jemerau at Tasik Chini in district of Kuantan, Pahang, East Coast of Peninsular Malaysia, about 75km from University Malaysia Pahang (UMP) . This study will focused by using the availability of Google Earth data in between 6 years of the changes. The sample location was collected where the river morphology change. The collection of data also include the hydrological data of the river and the land used by the government. Besides that, this study also will concentrate on the measurement of river cross section on site and the land used by site investigation.

1.5 Significant of Study

The results of this study provide benefits to the Kuantan area and to the larger scientific community in Tasik Chini. Locally this study will give information to educators and help administrators actualize administration procedures to reduce sedimentation. Toward the end of this study, the waterway morphology and zone that contributes high sedimentation to the downstream of the selected river could be resolved and examine. Other than that, it can be used to identify the problem based on the changes of morphology at identified area.

REFERENCES

- Chang Chun Kiat, Aminuddin Ab Ghani, Rozi Abdullah & Nor Azazi Zakaria. (2010). Sediment transport modeling for Kulim River e A case study, 2(October 2003).
- Department of Irrigation and Drainage. (2012). Urban Stormwater Management Manual for Malaya Estimation. Chapter2, 1-5.
- Edward J. Hickin. (1995). River geomorphology. *River Geomorphology*, 44(2), 255.
- Wang Sui-Ji & Ni Jin-Ren (2002). Straight river: its Formation and speciality, 72
- Hubert Chanson. (1999). Sediment transport: new approach and analysis. *The Hydraulics of Open Channel Flow*, 195–209.
- H. Mahabaleshwara & H.M. Nagabhushan. (2014). A Study on Soil Erosion and Its Impacts on Floods and Sedimentation. *International Journal of Research in Engineering and Technology*, 3(3), 443–451.
- Wilson. (1972). Seasonal sediment yield pattern of U.S rivers 84-91
- Martinez, Williams, Metoyer, Morris, & Berhane, (2009). Impact of Google Earth on Student Learning. 223-226
- Mohd Ekhwan Toriman, Mohd Khairul Amri Kamarudin, Mushrifah Hj Idris, Nor Rohaizah Jamil, Muhammad Barzani Gazim & Nor Azlina Abd Aziz.(2009). Sediment Concentration and Load Analyses at, 1(2), 43–50.
- Manan, Ismail (2008) A study of sediment load: case study at Parit Botak Channel, Batu Pahat, Johor, Malaysia
- Nadiatul Adilah Ahmad Abdul Ghani, Fatin Adnin & Mohamad Prim Nasir. (2013). Preliminary study on sediment load at Sungai Galing , Kuantan , Pahang.